



711 East Main • Lyons Kansas • 620-257-2331 • FAX 620-257-2334



**Haas UMC-750 5-Axis**

<b>Travel:</b>	
X Axis	30.0"
Y Axis	20.0"
Z Axis	20.0"
Rapid Feedrate	1,200 IPM
<b>Spindle:</b>	
Max Speed	10,000 RPM
Max Rating	30 HP
<b>Axis:</b>	5



**Haas VF-5SS Vertical**

<b>Travel:</b>	
X Axis	50.0"
Y Axis	26.0"
Z Axis	29.0"
Rapid Feedrate	1,200 IPM
<b>Spindle:</b>	
Max Speed	12,000 RPM
Max Rating	30 HP
<b>Axis:</b>	5



**Haas VF-6SS Vertical**

<b>Travel:</b>	
X Axis	64.0"
Y Axis	32.0"
Z Axis	30.0"
Rapid Feedrate	1,200 IPM
<b>Spindle:</b>	
Max Speed	12,000 RPM
Max Rating	30 HP
<b>Axis:</b>	5



**Haas VF-6SS Vertical**

<b>Travel:</b>	
X Axis	64.0"
Y Axis	32.0"
Z Axis	38.0"
Rapid Feedrate	1,200 IPM
<b>Spindle:</b>	
Max Speed	12,000 RPM
Max Rating	30 HP
<b>Axis:</b>	5



711 East Main • Lyons Kansas • 620-257-2331 • FAX 620-257-2334



Haas VF-8 Vertical

<b>Travel:</b>	
X Axis	64.0"
Y Axis	40.0"
Z Axis	30.0"
Rapid Feedrate	600 IPM
<b>Spindle:</b>	
Max Speed	7,500 RPM
Max Rating	30 HP
<b>Axis:</b>	4



Haas GR-712 Vertical

<b>Travel:</b>	
X Axis	145.0"
Y Axis	85.0"
Z Axis	11.0"
Rapid Feedrate	1,200 IPM
<b>Spindle:</b>	
Max Speed	10,000 RPM
Max Rating	15 HP
<b>Axis:</b>	3



Fadal 8030 Vertical

<b>Travel:</b>	
X Axis	80.0"
Y Axis	30.0"
Z Axis	30.0"
Rapid Feedrate	400 IPM
<b>Spindle:</b>	
Max Speed	10,000 RPM
Max Rating	22 HP
<b>Axis:</b>	3



Fadal 6030 Vertical

<b>Travel:</b>	
X Axis	60.0"
Y Axis	30.0"
Z Axis	30.0"
Rapid Feedrate	400 IPM
<b>Spindle:</b>	
Max Speed	10,000 RPM
Max Rating	22 HP
<b>Axis:</b>	5



711 East Main • Lyons Kansas • 620-257-2331 • FAX 620-257-2334



**Fadal 5020A Vertical**

<b>Travel:</b>	
X Axis	50.0"
Y Axis	20.0"
Z Axis	28.0"
Rapid Feedrate	400 IPM
<b>Spindle:</b>	
Max Speed	10,000 RPM
Max Rating	22 HP
<b>Axis:</b>	5



**Mori Seiki NH4000 Horizontal**

<b>Travel:</b>	
X Axis	22.0"
Y Axis	22.0"
Z Axis	24.8"
Rapid Feedrate	1,969 IPM
<b>Spindle:</b>	
Max Speed	14,000 RPM
Max Rating	25 HP
<b>Axis:</b>	4



**Mori Seiki NH5000 Horizontal**

<b>Travel:</b>	
X Axis	28.8"
Y Axis	23.6"
Z Axis	26.4"
Rapid Feedrate	1,969 IPM
<b>Spindle:</b>	
Max Speed	14,000 RPM
Max Rating	25 HP
<b>Axis:</b>	4



**Mori Seiki NH5000 Horizontal**

<b>Travel:</b>	
X Axis	28.8"
Y Axis	23.6"
Z Axis	26.4"
Rapid Feedrate	1,969 IPM
<b>Spindle:</b>	
Max Speed	14,000 RPM
Max Rating	25 HP
<b>Axis:</b>	5



711 East Main • Lyons Kansas • 620-257-2331 • FAX 620-257-2334



**Okuma MX-40HA Horizontal**

<b>Travel:</b>	
X Axis	22.0"
Y Axis	24.0"
Z Axis	22.0"
Rapid Feedrate	1,100 IPM
<b>Spindle:</b>	
Max Speed	7,000 RPM
Max Rating	15 HP
<b>Axis:</b>	4



**Cincinnati Maxim 400EP Horizontal**

<b>Travel:</b>	
X Axis	22.0"
Y Axis	20.0"
Z Axis	20.0"
Rapid Feedrate	1,100 IPM
<b>Spindle:</b>	
Max Speed	10,000 RPM
Max Rating	15 HP
<b>Axis:</b>	4



**Johnford SL-300 Turning Center**

<b>Travel:</b>	
X Axis	7.2"
Z Axis	21.2"
Rapid Feedrate	944 IPM
<b>Spindle:</b>	
Max Speed	4,500 RPM
Max Rating	20 HP
<b>Axis:</b>	2



**Hwacheon Cutex 240B Turning Center**

<b>Travel:</b>	
X Axis	22.0"
Z Axis	22.0"
Rapid Feedrate	1,400 IPM
<b>Spindle:</b>	
Max Speed	5,000 RPM
Max Rating	25 HP
<b>Axis:</b>	2