



711 East Main • Lyons Kansas • 620-257-2331 • FAX 620-257-2334

| | |
|-----------------|------------|
| Travel: | |
| X Axis | 22" |
| Y Axis | 22" |
| Z Axis | 24" |
| Spindle: | |
| Taper size | CAT 40 |
| Max speed | 14,000 RPM |
| Max rating | 24 HP |
| Axis: | 4 |



Mori Seiki NH4000

| | |
|-----------------|------------|
| Travel: | |
| X Axis | 24" |
| Y Axis | 23" |
| Z Axis | 26" |
| Spindle: | |
| Taper size | CAT 40 |
| Max speed | 14,000 RPM |
| Max rating | 24 HP |
| Axis: | 4 |



Mori Seiki NH5000

| | |
|-----------------|------------|
| Travel: | |
| X Axis | 24" |
| Y Axis | 23" |
| Z Axis | 26" |
| Spindle: | |
| Taper size | CAT 40 |
| Max speed | 14,000 RPM |
| Max rating | 24 HP |
| Axis: | 5 |



Mori Seiki NH5000

| | |
|-----------------|-----------|
| Travel: | |
| X Axis | 22" |
| Y Axis | 24" |
| Z Axis | 22" |
| Spindle: | |
| Taper size | CAT 40 |
| Max speed | 7,000 RPM |
| Max rating | 15 HP |
| Axis: | 4 |



Okuma MX-40HA

| | |
|-----------------|------------|
| Travel: | |
| X Axis | 22" |
| Y Axis | 20" |
| Z Axis | 20" |
| Spindle: | |
| Taper size | CAT 40 |
| Max speed | 10,000 RPM |
| Max rating | 15 HP |
| Axis: | 4 |



Cincinnati Maxim 400EP



711 East Main • Lyons Kansas • 620-257-2331 • FAX 620-257-2334

| | |
|-----------------|------------|
| Travel: | |
| X Axis | 145" |
| Y Axis | 85" |
| Z Axis | 11" |
| Spindle: | |
| Taper size | CAT 40 |
| Max speed | 10,000 RPM |
| Max rating | 15 HP |
| Axis: | 3 |



Haas GR-712

| | |
|-----------------|------------|
| Travel: | |
| X Axis | 50" |
| Y Axis | 26" |
| Z Axis | 29" |
| Spindle: | |
| Taper size | CAT 40 |
| Max speed | 12,000 RPM |
| Max rating | 30 HP |
| Axis: | 5 |



Haas VF-5SS

| | |
|-----------------|--------------|
| Travel: | |
| X Axis | 64" |
| Y Axis | 40" |
| Z Axis | 30" |
| Spindle: | |
| Taper size | CAT 50 |
| Max speed | 7,500 RPM |
| Max rating | 30 HP Geared |
| Axis: | 3 |



Haas VF-8

| | |
|-----------------|------------|
| Travel: | |
| X Axis | 60" |
| Y Axis | 30" |
| Z Axis | 30" |
| Spindle: | |
| Taper size | CAT 40 |
| Max speed | 10,000 RPM |
| Max rating | 22 HP |
| Axis: | 5 |



Fadal 6030 VMC

| | |
|-----------------|------------|
| Travel: | |
| X Axis | 80" |
| Y Axis | 30" |
| Z Axis | 30" |
| Spindle: | |
| Taper size | CAT 40 |
| Max speed | 10,000 RPM |
| Max rating | 22 HP |
| Axis: | 3 |



Fadal 8030 VMC



711 East Main • Lyons Kansas • 620-257-2331 • FAX 620-257-2334

| | |
|-----------------|------------|
| Travel: | |
| X Axis | 50" |
| Y Axis | 20" |
| Z Axis | 28" |
| Spindle: | |
| Taper size | CAT 40 |
| Max speed | 10,000 RPM |
| Max rating | 22 HP |
| Axis: | 5 |



Fadal 5020A VMC

| | |
|-----------------|-----------|
| Travel: | |
| X Axis | 10" |
| Z Axis | 20" |
| Spindle: | |
| Max speed | 3,800 RPM |
| Max rating | 30 HP |
| Milling Head | 7 HP |
| Axis: | 2 |



Okuma Captain L370-M

| | |
|-----------------|-----------|
| Travel: | |
| X Axis | 7" |
| Z Axis | 21" |
| Spindle: | |
| Max speed | 4,500 RPM |
| Max rating | 20 HP |
| Axis: | 2 |



Johnford SL-300